

ASBESTOS FIBRE IDENTIFICATION CERTIFICATE

| | | | |
|---------------------------|---|---------------------------------|-------------------|
| Job Reference No.: | J011571 | Report Date: | 9 Feb 2013 |
| Client: | Safeguard Asbestos Services Limited | Source: | ASI Environmental |
| Client Address: | PO Box 311 Alton Hampshire GU34 9HA | No. of Samples Received: | 18 |
| FAO: | Chris Anton | Date Received: | 8 Feb 2013 |
| Site Address: | Porchester Sailing Club Waterside Lane Castle Street Porchester Hants | Date Analysed: | 9 Feb 2013 |
| | | Client Job Number | N/A |

Method of Analysis

Sample identification was carried out using Polarised Light Microscopy coupled with McCrone Dispersion staining techniques in accordance with the documented in-house method based on HSE guidance notes HSG248. (*Asbestos: The Analysts Guide for Sampling Analysis and Clearance Procedures*).

| ASI Sample No. | Client Sample No. | Location | Product Type* | Asbestos Type Detected |
|----------------|-------------------|---|---------------------------|------------------------|
| BS005840 | B01 | Entrance porch ceiling panels | Insulating Board | NADIS |
| BS005841 | B02 | Gents toilets textured ceiling coating | Textured Coating | Chrysotile |
| BS005842 | B03 | Gents toilets sink pad | Well Bound Material | Chrysotile |
| BS005843 | B04 | Gents shower room textured ceiling coating | Textured Coating | NADIS |
| BS005844 | B05 | Ladies changing room grey floor tile | Thermoplastic Floor Tiles | Chrysotile |
| BS005845 | B06 | Canteen area blue floor tile | Thermoplastic Floor Tiles | Chrysotile |
| BS005846 | B07 | Canteen area white floor tile | Thermoplastic Floor Tiles | Chrysotile |
| BS005847 | B08 | Corridor adjacent bar/kitchen panel over door | Insulating Board | NADIS |
| BS005848 | B09 | Kitchen sink pad | Well Bound Material | Chrysotile |
| BS005849 | B10 | Store adjacent cellar textured coating | Textured Coating | NADIS |

SAMPLE ANALYSIS REPORT (CONTINUATION)

| ASI Sample No. | Client Sample No. | Location | Product Type* | Asbestos Type Detected |
|----------------|-------------------|---|---------------------------|------------------------|
| BS005850 | B11 | Store adjacent cellar sink pad | Well Bound Material | Chrysotile |
| BS005851 | B12 | Corridor toilet floor tile | Vinyl Floor Tile | NADIS |
| BS005852 | B13 | Upper bar sink pads | Well Bound Material | Chrysotile |
| BS005853 | B14 | External roof undercloaking | Asbestos Cement | Chrysotile |
| BS005854 | B15 | External store 2 ceiling panels | Asbestos Insulating Board | Amosite |
| BS005855 | B16 | Area behind stores 1, 2 & 3 cement debris | Asbestos Cement | Chrysotile |
| BS005856 | B17 | Acetylene store roof sheet | Asbestos Cement | Chrysotile |
| BS005857 | B18 | External toilet roof tile | Asbestos Cement | Chrysotile |

Sample Notes:

NADIS indicates there is NO Asbestos detected in sample

Analysed By: **Magda Jackson** Lab Analyst
 Authorised By: **Magda Jackson** Lab Analyst

Authorised Signature:



ASI Environmental does not accept any responsibility for information provided by the client or for the manner in which samples are taken by the client and delivered to ASI Environmental for analysis.

Notes

1. Sample(s) collected are analysed for the presence of six types of asbestos fibres - Crocidolite-blue, Amosite-brown, Chrysotile-white, Anthophyllite, Actinolite and Tremolite.
2. Opinions and interpretations are identified by an * are outside the scope of the laboratory's UKAS accreditation.